Figure F6. Coal supply regions



APPALACHIA
- Northern Appalachia
- Central Appalachia
- Southern Appalachia

INTERIOR
- Eastern Interior
- Western Interior
- Gulf Lignite

NORTHERN GREAT PLAINS
- Dakota Lignite
- Western Montana
- Wyoming, Northern Powder River Basin
- Wyoming, Southern Powder River Basin
- Western Wyoming

OTHER WEST
- Rocky Mountain
- Southwest
- Northwest

Source: U.S. Energy Information Administration, Office of Energy Analysis.